

Work Order ID 58330

May 3, 2010 1:31:45 PM



Page 1

Item ID: K10002

Accept



Setup Start



Revision ID:

Item Name: Pod Kit, 350

Stop



Start Date: 5/03/10 Start Qty: 1.00



Cust Item ID:

Required Date: 5/04/10 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

K10002

Rev A

100

0.00



DOCUMENT CONTROL

DC

Document Control

Memo

Create White labels only per PPP K10002

0.00

CHG 002

for BG 10/05/04

Work Order ID 58330

May 3, 2010 1:31:45 PM



Page 2

Item ID: K10002

Accept



Setup Start



Revision ID:

Item Name: Pod Kit, 350

Start Date: 5/03/10 Start Qty: 1.00



Cust Item ID:

Required Date: 5/04/10 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

110



Packaging

Packaging

Operation
Description

Pick Kit

Set Up/
Run Hours

0.00

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

10-5-4
S

Memo
PULL FROM STOCK:
1 X K10002 B53037

REMOVE 4 X D2230-1 B 51566
REMOVE 4 X D2230-3 B 53450

REPLACE WITH
4 X D3910-3 B 57811
4 X D4091-1 B 57250 (1X) 58098 2X

REMOVE 4 X D2856-400-720 B 52563
REPLACE WITH
8 X D3984-030 B 53707

ALSO ADD TO KIT:

16 X AN4-14A B 114494
32 X NAS1149D0463J B 113706
16 X MS21042L4 B 114108

10-5-4
S

120



QC

Quality Control

QC4- 100% Inspect kits for completeness

0.00

0.00

S 10-5-4
EC

Work Order ID 58330

May 3, 2010 1:31:46 PM



Page 3

Item ID: K10002

Accept



Setup Start



Revision ID:

Item Name: Pod Kit, 350

Stop



Start Date: 5/03/10 Start Qty: 1.00



Cust Item ID:

Required Date: 5/04/10 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan:

Date: Tooling:

Date:

Run Start



QC:

Date: SPC (Y/N):

Date:

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run HoursDraw
NumberDraw
Rev.Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130



Packaging

0.00

Packaging

Memo

0.00

Rev-0

140



QC21- Final Inspection - Work Order Release

0.00

QC
Quality Control

Memo

0.00

MF

10-5-06